

TO INFORM YOU

PRODUCT SUPPORT BULLETIN # 305

TO: AUTHORIZED *Portable Electric Tool* SERVICE STATIONS
BRANCH OFFICE/SERVICE CENTERS, BRANCH MANAGERS
REGIONAL MANAGERS, DISTRICT MANAGERS, SALES SUPPORT REPRESENTATIVES

FROM: Corbert A. Garb - National Service Manager

TOOL(S)/PRODUCT(S) AFFECTED:

23-66-1666, 23-66-2121, 23-66-2145 SWITCH

14-46-0305 SWITCH SERVICE KIT

14-46-5365 SWITCH SERVICE KIT

23-66-1667 SWITCH SERVICE KIT

0102-1, 0141-1, 0222-1, 0227-1, 0228-6, 0229-1, 0230-1, 03231-6, 0237-1, 0238-1, 0239-1 PISTOL GRIP HOLE-SHOOTER

0124-1, 0224-1, 0225-1, 0234-6, 0235-6, 0244-1, 0233-20, 0232-20 1/4"-3/8" & 1/2" MAGNUM[®] HOLE-SHOOTER

5391-1, 5392-6 3/8" PISTOL GRIP HAMMER DRILL


5370-6, 5374-1, 5376-6 MAGNUM[®] HAMMER DRILL

5362-6, 5366-6, HAWK / FALCON ROTARY HAMMER

6543-1, 6583-1, 6747-1, 6757-1, 6760-1, 6760-6, 6767-6, 6798-1, 6583-1, 6783-1, 6798-6 PISTOL GRIP SCREW-SHOOTERS

6749-1, 6793-1, 6794-1 MAGNUM[®] SCREW-SHOOTER

SUBJECT: LEAD WIRE REMOVAL



Switch Bottom

AS A PRODUCT IMPROVEMENT THE 23-66-1666, 23-66-2121, & 23-66-2145 SWITCH ARE SEALED AGAINST CONTAMINATION.

THERE ARE FIVE (5) HOLES IN THE BOTTOM OF THE 23-66-1666, 23-66-2121 & 23-66-2145 SWITCH TO RECEIVE LEAD WIRES.

NEXT TO THESE HOLE ARE 5 SMALLER HOLES THAT HAVE A BOTTOM OR THIN PLASTIC 'WINDOW' IN THEM

TO REMOVE THE LEAD WIRES FROM THE SWITCH, IT IS NECESSARY TO BREAK THROUGH THE THIN PLASTIC 'WINDOWS' OF THESE SMALL HOLES, TO ALLOW YOU TO INSERT A PROBE TO RELEASE THE WIRE(S).

AFTER REPLACING OR REINSERTING LEAD WIRES INTO THE SWITCH, THE SMALL 'WINDOW' HOLES THAT WERE BROKEN TO INSERT THE PROBE, MUST BE COVERED WITH 'RTV' SILICONE ADHESIVE/SEALANT (P/N 44-22-0070 - 2.8 FLUID OZ TUBE) TO PREVENT UNNECESSARY CONTAMINATION FROM REACHING THE INTERNAL COMPONENTS OF THE SWITCH AND EARLY SWITCH FAILURE.

This bulletin is for informational purposes.