SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS

28 VOLT BATTERY

CATALOG NO.	48-11-2830	SERIAL NUMBER	**A71A, A71B, A71C, A71D**

REVISED BULLETIN

DATE
Feb. 2007

WIRING INSTRUCTION

EXAMPLE:
Component Parts (Small #)
Are Included When Ordering
The Assembly (Large #).

00 | 0

FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	10-20-3620	Front Label	(1)
2	10-15-1290	Service Nameplate	(1)

FIG.	NOTES
1, 2	A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or name plate.

Milwaukee®

SERVICE PARTS LIST

BULLETIN NO.
54-04-7011

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS

	REVISED BULLETIN	DATE
M28 BATTERY	54-04-7010	Sept. 2010
CATALOG NO. 48-11-2830	SERIAL NUMBER **C71E**	WIRING INSTRUCTION

EXAMPLE:
Component Parts (Small #)
Are Included When Ordering
The Assembly (Large #).

| 00	0

**NOTE:** Some battery nameplates were stamped with a serial number prefix and break of **C48A**.

FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	10-20-4550	Fuel Gauge Label (Front of tool)	(1)
2	12-20-2900	Service Nameplate (Bottom of tool)	(1)

FIG.	NOTES
1, 2	A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or name plate.

SERVICE PARTS LIST

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS	REVISED BULLETIN 54-04-7011

M28 BATTERY

CATALOG NO.	**48-11-2830**	SERIAL NUMBER	**C71F**

REVISED BULLETIN 54-04-7011 | DATE Nov. 2010

WIRING INSTRUCTION

EXAMPLE:

00 / 0̄

Component Parts (Small #)
Are Included When Ordering
The Assembly (Large #).

| FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	10-20-4550	Fuel Gauge Label (Front of tool)	(1)
2	12-20-2900	Service Nameplate (Bottom of tool)	(1)

FIG.	NOTES
1, 2	A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or name plate.

Looking for <u>dependable power tools</u>? Rely on <u>Milwaukee for quality and long-lasting products.</u>