



50 ft LASER & TAPE MEASURE

LTM1 QUICK START GUIDE

1

Install included batteries properly

2

Press once to find target

Press again for measurement

REFERENCE

WALL

50ft

Laser measures from back of unit

Tape Lock Release Button on bottom

WARNING DO NOT RETRACT TAPE AT HIGH SPEED