

 Make a clean cut of 1/8" steel tape where Leader will be attached.



2. Separate Leader and Twist Cap. Slide Twist Cap onto to tape as shown.



Heat tape to dull red and completely bend tip over 3/16" using pliers. Allow tape to fully cool.



 Slide Twist Cap to the end of the tape (over the bend) and reconnect tightly onto Leader.

## KLEIN TOOLS<sub>®</sub>

## **Fish Tape Leader**

## Use with 1/8" wide steel fish tapes

Utilícela con cintas pasadoras de acero anchas de 1/8 de pulgada

Utiliser avec des rubans de tirage en acier de 1/8 po de large

## WARNINGS

**A WARNING:** Always wear approved eye protection.

A WARNING: Never use on or near live electrical circuits.

Discover other wire and cable tools on our website.