

FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.	FIG.	NOTES
1	31-12-0061	Depth Gauge Twist Assembly	(1)	8	A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.
2	31-76-0020	Shroud Collar Kit	(1)		
3	31-12-0060	Shroud Collar Twist Cap Assembly	(1)		
4		Screw	(1)		
5		Washer	(1)		
6		Washer	(1)		
7		Shroud Collar	(1)		
8	10-20-1286	Nameplate (Not Shown)	(1)		