



## Model BO5030/K Parts List

A = Standard Equipment

○ = Circuit Diagram

Fig.	Part No.	Description	Q'ty	Unit	
1	265995-6	TAPPING SCREW 4X18	3	PC.	
2	450071-1	TOP COVER	1	PC.	
3	265995-6	TAPPING SCREW 4X18	2	PC.	
5	687063-9	STRAIN RELIEF	1	PC.	
6	682502-4	CORD GUARD 8-85	1	PC.	
7	664064-4	POWER SUPPLY CORD (2x18x8; SJ)	1	PC.	
8	191927-6	CARBON BRUSH CB-407	1	SET	
9	643995-0	BRUSH HOLDER	2	PC.	
11	651527-9	SWITCH	1	PC.	
12	424039-3	SWITCH COVER	1	PC.	
13	450671-7	MOTOR HOUSING	1		
14	865589-3	BO5030 NAME PLATE	1		
15	633671-4	FIELD 115V	1		
16	266147-2	TAPPING SCREW 4X55	2	PC.	
17	210017-7	BALL BEARING 607DDW	1	PC.	
18	681652-2	INSULATION WASHER	1	PC.	
19	515731-3	ARMATURE ASS'Y 115V	1		
	D10	INC. 17,18,20,21			
20	267806-1	WASHER 9	1	PC.	
21	211092-6	BALL BEARING 629DDW	1	PC.	
22	450672-5	BRACKET	1		
23	265995-6	TAPPING SCREW 4X18	4	PC.	
24	241673-2	FAN 88	1		
25	267164-5	FLAT WASHER 15	1	PC.	
26	188579-2	SKIRT L/R SET	1		
	D10	INC. 28			
27	265995-6	TAPPING SCREW 4X18	2	PC.	
28	188579-2	SKIRT L/R SET	1		
	D10	INC. 26			
29	318304-9	BEARING BOX	1		
30	211228-7	BALL BEARING 6202DDW	1	PC.	
31	424131-5	BRAKE RING	1		
32	318303-1	BEARING BOX COVER	1		
33	253739-6	FLAT WASHER 4	1	PC.	
34	911128-8	PAN HEAD SCREW M4X16	1	PC.	
35	743081-8	PAD 123	1	PC.	
36	911128-8	PAN HEAD SCREW M4X16	3	PC.	
A	A01	166078-4	DUST BAG	1	PC.
A	A02	257202-1	RING 25	1	PC.
A	A03	416063-0	DUST BAG NOZZLE	1	PC.
A	A04	416064-8	DUST NOZZLE	1	PC.
A	A05	794520-1	ABRASIVE DISC 125 #120	1	SET
A	A06	183782-0	PLASTIC CARRYING CASE	1	PC.
	C10	A00798-8	LATCH	2	PC.
	C20	819144-3	MAKITA LOGO LABEL	1	PC.
D01	654069-2	RECEPTACLE	2	PC.	
D02	654558-7	INSULATED CONNECTOR	1	PC.	
	BO5030	TOOL W/O CASE			