



QUICKSTART

SK103P


- 1 On/Set key
- 2 Pulse key
- 3 Lock switch
- 4 Locked
- 5 Laser active
- 6 Pulse/Power save mode on
- 7 Laser line horizontal
- 8 Laser line vertical
- 9 Laser horizontal and vertical line
- 10 Laser all points
- 11 Laser all lines and points






Batteries



Transportation and lock



Self leveling



ON 1x

self levelling




ON 2s OFF

self levelling



ON 2x

self levelling




ON 2s OFF



	LASER	2	
IEC 60825-1:2014	$\lambda=635\text{nm}$	Pav.=0.95m	$W_{tp}=50\mu\text{s}$

ON 3x


self levelling  



ON 2s OFF

ON 4x

self levelling  



ON 2s OFF

ON 5x


self levelling  



ON 2s OFF

PULSE **ON** 1x

self levelling  



ON 2s OFF

ON 1x —

ON 2x

lock  



Learn more about measuring and layout tools we have.