



## Model XSS01/XSS01Z Parts list

A = Standard Equipment

O = Circuit Diagram

Item#	Part#	Description	Q'ty	Unit
001	265995-6	TAPPING SCREW 4X18	6	PC.
002	141470-5	HANDLE COVER COMPLETE	1	PC.
003	650631-1	SWITCH	1	PC.
004	231469-9	COMPRESSION SPRING 4	1	PC.
005	419322-1	LOCK OFF LEVER	1	PC.
006	620088-0	POWER SUPPLY CIRCUIT	1	PC.
007	231469-9	COMPRESSION SPRING 4	1	PC.
009	644808-8	TERMINAL	1	PC.
010	419176-6	SWITCH LEVER	1	PC.
011	265995-6	TAPPING SCREW 4X18	2	PC.
012	419281-9	REAR COVER	1	PC.
013	643941-3	BRUSH HOLDER CAP	2	PC.
014	CB441	CARBON BRUSH CB-441 (195022-4)	1	SET
015	911263-2	PAN HEAD SCREW M5X40	3	PC.
016	643895-4	BRUSH HOLDER	1	PC.
017	643896-2	BRUSH HOLDER	1	PC.
018	815E90-8	XSS01 NAME PLATE	1	
019	142460-1	MOTOR HOUSING COMPLETE	1	
	C10 802U29-6	CAUTION LABEL	1	
020	638107-8	YOKE UNIT	1	PC.
021	419285-1	BAFFLE PLATE	1	PC.
022	266292-3	TAPPING SCREW 4X65	2	PC.
023	210023-2	BALL BEARING 627DDW	1	PC.
024	519173-3	ARMATURE ASS'Y 18V	1	PC.
	D10	INC. 23,25,26		
025	241869-5	FAN 55	1	PC.
026	211061-7	BALL BEARING 6000LLB	1	PC.
027	346059-6	SHAFT LOCK	1	PC.
028	233092-6	COMPRESSION SPRING 5	1	PC.
029	911118-1	PAN HEAD SCREW M4X12	2	PC.
030	419284-3	BLOWER NOZZLE	1	PC.
031	188045-9	BLADE CASE SET	1	PC.
	C10 213434-0	O RING 26	1	PC.
	D10	INC. 32		
032	819217-2	MAKITA LOGO PLATE	1	PC.
033	262049-0	RUBBER RING 6	1	PC.
034	251368-9	+ COUNTERSUNK SCREW M6	1	PC.
035	210028-2	BALL BEARING 606ZZ	1	PC.
036	961052-5	RETAINING RING S-12	1	PC.
037	227156-6	SPUR GEAR 52	1	PC.
038	257173-2	RING 12	1	PC.
039	213512-6	O RING 39	1	PC.
040	265034-2	+ COUNTERSUNK HEAD SCREW M5X16	2	PC.
041	318009-1	BEARING BOX	1	PC.
042	211131-2	BALL BEARING 6001DDW	1	PC.
043	324626-7	SPINDLE	1	PC.
044	285845-9	BEARING RETAINER 19-29	1	PC.
045	345469-4	THICKNESS RING	1	PC.
046	231821-1	TENSION SPRING 3	1	PC.

047	419280-1	SAFETY COVER	1 PC.
048	961152-1	RETAINING RING (EXT) S-34	1 PC.
049	224151-7	INNER FLANGE 40	1 PC.
050	224275-9	OUTER FLANGE 40	1 PC.
051	266133-3	HEX. SOCKET HEAD BOLT M6X20	1 PC.
052	631694-6	LED CIRCUIT	1 PC.
053	419341-7	CONNECTOR BOX	1 PC.
054	419282-7	LIGHT COVER	1 PC.
055	266026-4	TAPPING SCREW BIND CT 4X12	2 PC.
056	961014-3	STOP RING E-8	1 PC.
057	272229-0	LEVER 40	1 PC.
058	252158-3	HEX.NUT M6	1 PC.
059	941151-9	FLAT WASHER 6	1 PC.
060	345658-1	DEPTH GUIDE	1 PC.
061	252103-8	HEX. LOCK NUT M5-8	1 PC.
062	345657-3	ANGULAR GUIDE	1 PC.
063	317986-4	STOPPER	1 PC.
064	213062-1	O RING 9	1 PC.
065	265084-7	+ TRUSS HEAD SCREW M5	1 PC.
066	266194-3	FLAT HEAD SCREW M6X90	1 PC.
067	256480-0	SHOULDER PIN 6-7	1 PC.
068	256480-0	SHOULDER PIN 6-7	1 PC.
069	266264-8	H.S.SET SCREW(FLAT POINT)M5X6	1 PC.
070	251919-8	CAP SQUARE NECK BOLT M6X20	1 PC.
071	231007-7	COMPRESSION SPRING 6	1 PC.
072	251896-4	SCREW M5X20	1 PC.
073	941151-9	FLAT WASHER 6	1 PC.
076	252133-9	HEX. NUT M6	1 PC.
077	961014-3	STOP RING E-8	1 PC.
078	272251-7	LEVER 30	1 PC.
079	266264-8	H.S.SET SCREW(FLAT POINT)M5X6	1 PC.
080	266229-0	H.S.SET SCREW(CUP POINT)M5X8	1 PC.
081	154831-0	BASE COMPLETE	1 PC.
C10	816850-1	SCALE PLATE	1 PC.
082	266229-0	H.S.SET SCREW(CUP POINT)M5X8	1 PC.
085	253186-1	FLAT WASHER 7	1 PC.
A01	164095-8	GUIDE RULE	1 PC.
A02	783203-8	HEX. WRENCH 5	1 PC.
A03	A-85092	T.C.T.SAW BLADE 165X24TX15.88	1 PC.
A04	141353-9	PLASTIC CARRYING CASE COMPLETE	1 PC. (XSS01)
C10	163455-1	LATCH	2 PC. (XSS01)
C20	419360-3	HANDLE	1 PC. (XSS01)
A05	***DC18RC	DC18RC FAST CHARGER	1 PC. (XSS01)
A06	BL1830	BATTERY BL1830 SET	2 SET (XSS01)
A08	450128-8	BATTERY COVER	1 PC. (XSS01)
E01	620258-1	CONTROLLER	1
D01	654208-4	RECEPTACLE	2 PC.