



TO INFORM YOU

PRODUCT
SUPPORT
BULLETIN # 188

TO: Authorized Service Stations
Branch Office/Service Centers
Branch/Service Center Managers
Regional Managers
District Sales Managers

FROM: Corbert A. Garb - National Service Manager

TOOL(S)/PRODUCT(S) AFFECTED: 1001-1, 1007-1, 1101-1, 1107-1, 1201-1, 1250-1 D-HANDLE DRILLS, 5388, 5398 D-HANDLE HAMMER DRILLS, & 6507, 6508, 6511, 6512, SAWZALLS USING 23-66-0167 or 23-66-1470 TRIGGER SWITCH

SUBJECT: 14-46-1001 D-HANDLE FOAM SLUG KIT

14-46-1001 Foam Slug Kit is a new service replacement part, that contains 10 foam slugs. Four (4) foam slugs are to be placed in the handles of all d-handle tools listed above, to help block airflow and contamination of the switch, lessening the potential for failure of the switch.

Two (2) foam slugs should be placed in the *left handle half* and two (2) foam slugs should be placed in the *right handle half* (directly opposite each other) at the locations shown in the drawing on the reverse side.

(Note: a change is being made to the *right hand handle half* of current production d-handle tool handles, adding extra internal ribs that will reduce the amount of slugs required per tool from 4 to 2.)

This bulletin is for informational purposes; please note on Service Parts Lists 54-08-1087, -1148, -1187, -1203, -1213, -2068, 54-24-1307, -1324, 54-40-0105, -0321, -4147 & -4258.

