

Size	Length	Qty/Box	Part No.
0	)		
<b>Stainless Car</b>	riage Bolts	ş	
14-20	1	50	12-1501
	11/2	50	12-1503
	2	50	12-1505
	21/2	50	12-1507
	3	50	12-1509
%e-18	2	50	12-1519
	21/2	50	12-1520
	5	25	12-1522
<del>3</del> ⁄ε-16	21/2	50	12-1533

art No.	
	St
2-1501	
2-1503	
2-1505	
2-1507	
2-1509	
2-1519	
2-1520	
2-1522	
2-1533	

Size	Length	Qty/Box	Part No.
Stainless Hex H	lead Cap Screw	s Continued	
3/6-16	34	50	12-1380
	1	50	12-1382
	11/4	50	12-1383
	11/2	50	12-1384
	134	50	12-1385
	2	50	12-1386
	21/2	50	12-1388
	3	50	12-1390
1/2-13	11/4	25	12-1414
	11/2	25	12-1415
	21/2	25	12-1419








00			
Hex Machine Scree	w Nuts Stainles	5	
6-32	100	12-2752	
8-32	100	12-2753	
10-24	100	12-2754	
10-32	100	12-2756	
100 per box.			

etric Stainless Hex Nuts (Standard)			
6mm	50	12-3709	
8mm	50	12-3710	
10mm	25	12-3711	





Elevator Bolts Mild Steel			
14 x 11/2	100	12-4104	
14 x 2	100	12-4105	
1/4 x 21/2	100	12-4106	
1/4 x 3	100	12-4107	
5/16X 11/2	50	12-4108	




Metric SS Hex Head Cap Screws				
6	35MM	25	12-3703	
10	25MM	10	12-3707	



Stainless Hex Head Cap Screws				
14-20	1/2	100	12-1338	
	34	100	12-1340	
	11/4	100	12-1343	
	11/2	100	12-1344	
	2	100	12-1346	
	21/2	100	12-1348	
	3	100	12-1350	
	31/2	50	12-1352	
	4	50	12-1353	
<del>5</del> 16-18	34	50	12-1360	
	1	50	12-1362	
	11/4	50	12-1363	
	11/2	50	12-1364	
	1%	50	12-1365	
	2	50	12-1366	
	21/2	50	12-1368	
	3	50	12-1370	
	31/2	50	12-1372	
Continued On Next Column				



**Stainless Lag Bolts** 



Cotter Pin		70	
1/16	1/2	100	12-2852
	34	100	12-2853
	1	100	12-2854
	11/2	100	12-2856
3/32	34	100	12-2860
	1	100	12-2861
	11/2	100	12-2863
	2	100	12-2865
1/8	1	100	12-2869
	11/4	100	12-2870
	11/2	100	12-2871
	2	100	12-2873
	3	100	12-2875
5/32	1	100	12-2877
	114	100	12-2878
	11/2	100	12-2879
	2	100	12-2881
	1		n Next Column



<b>Brass Hex He</b>	Brass Hex Heavy Jam or Full Nut			
¾-10	Jam	ea.	12-3521	
7/6−9	Jam	ea.	12-3522	
1-8	Jam	ea.	12-3523	
11/6-7	Jam	ea.	12-3524	
11/4-7	Jam	ea.	12-3525	
11/2-6	Jam	ea.	12-3526	
1¾-5	Jam	ea.	12-3527	
1/2-13	Heavy Full	ea.	12-3533	
34-10	Heavy Full	ea.	12-3535	
7/6−9	Heavy Full	ea.	12-3536	
1-8	Heavy Full	ea.	12-3537	
11/6-7	Heavy Full	ea.	12-3538	
11/4-7	Heavy Full	ea.	12-3539	
11/2-6	Heavy Full	ea.	12-3540	
134-5	Heavy Full	ea.	12-3541	
1/2-13	Jam	ea.	12-3519	





100 per box.



12-2791

Stainless Wing Nut	
14-20	12-2783
100 per box.	



Blind Rivets			
Aluminum Dia.	Grip		
1/4	¾6 to ¼	100	12-4117
	5/16 to 3/8	100	12-4118
346	1/2 to 1/4	100	12-4119
	1/4 to 3/4	100	12-4120
	% to 1/2	100	12-4121
	% to 34	100	12-4123
Stainless Dia.	Grip		
1/4	¾6 to ¼	100	12-4125
	1/8 to 1/4	100	12-4126
346	1/2 to 1/4	100	12-4127
	1/4 to 3/4	100	12-4128



Length Qty/Box Part No.

Stainless Flat (Phillips)	t Head Mac	hine Scre	WS
8-32	-1	100	12-2420
10-24	1	100	12-2428
	1%	100	12-2429
	11/2	100	12-2430
	2	100	12-2432
1/4-20	34	100	12-2380
	1	100	12-2381
	11/4	100	12-2382
	11/2	100	12-2383
	2	100	12-2385
	21/2	100	12-2387
	3	100	12-2388
54s-18	34	50	12-2391
	1	50	12-2392
	11/2	50	12-2393
	2	25	12-2394





Stainless Ste (Phillips)	el Oval Ma	chine Scre	rws
8-32	34	100	12-2476
	1	100	12-2477
	2	100	12-2481
10-24	34	100	12-2484
	1	100	12-2485
	11/2	100	12-2487
	2	100	12-2489
	3	100	12-2491
10-32	11/2	100	12-2497
14-20	1	100	12-2447
	11/2	100	12-2449
	2	100	12-2451
	21/2	100	12-2452
	3	100	12-2453
	4	100	12-2455





Stainless Rou (Phillips)	md Head M	lachine S	crews
8-32	34	100	12-2580
	1	100	12-2581
10-24	34	100	12-2586
	1	100	12-2587
1/4-20	1/2	100	12-2564
	34	100	12-2565
	1	100	12-2566
	11/4	100	12-2567
	21/2	100	12-2571



Stainless Pan Head Machine Screws		
(Phillips) 10	per box.	
8-32	1/2	12-2537
1	34	12-2539
	1	12-2540
	11/2	12-2542
10-24	1/2	12-2546
	34	12-2547
	1	12-2548
	11/4	12-2549
	11/2	12-2550
	2	12-2552
10-32	1/2	12-2556
	34	12-2557
	1%	12-2559
14-20	1/2	12-2501
	34	12-2502
	1	12-2503
	195	12-2505
	2	12-2507
	21/2	12-2508
	3	12-2509
	4	12-2511



Stainless Flat (Phillips) 100	Type A Tappi per box.	ng Screws
4	1/2	12-1837
	34	12-1839
6	1/2	12-1842
	34	12-1844
	1	12-1845
	134	12-1846
	11/2	12-1847
8	1/2	12-1850
	34	12-1852
	1	12-1854
	11/4	12-1855
	11/2	12-1856
	134	12-1857
	2	12-1858
10	34	12-1863
	1	12-1864
	11/4	12-1865
	11/2	12-1866
	2	12-1868
	21/2	12-1869
	3	12-1870
12	34	12-1873
	1	12-1874
	11/2	12-1876
	2	12-1878
14	1	12-1884
	11/2	12-1886
	2	12-1888

Size   Length   Qty/Box   Part No.
Stainless Oval Type A Tapping Screws (Phillips) 100 per box.   6    ½
(Phillips) 100 per box.  6 ½ 12-1897  34 12-1899  1 12-1900
(Phillips) 100 per box.  6 ½ 12-1897  34 12-1899  1 12-1900
(Phillips) 100 per box.  6 ½ 12-1897  34 12-1899  1 12-1900
(Phillips) 100 per box.  6 ½ 12-1897  34 12-1899  1 12-1900
6 ½ 12-1897 ¾ 12-1899 1 12-1900
34 12-1899 1 12-1900
1 12-1900
116 12-1002
172 12-1302
8 1/2 12-1905
% 12-1906
¾ 12-1907
1 12-1909
114 12-1910
1½ 12-1911
2 12-1913
3 12-1915
10 ¾ 12-1918
1 12-1919
1¼ 12-1920
1½ 12-1921
1¾ 12-1922
2 12-1923
3 12-1925
12 ¾ 12-1928
1 12-1929
1¼ 12-1930
1½ 12-1931
2 12-1933
21/2 12-1934
14 1 12-1939
1¼ 12-1940
1,1
1½ <b>12-1941</b>

ainless Pan He	ad Type A Tapping Screw

Stainless Par (Phillips) 100		A Tapping Screws
6	3/8	12-1952
	1/2	12-1953
	34	12-1955
	1	12-1956
8	36	12-1960
	1/2	12-1961
	56	12-1962
	34	12-1963
	1	12-1964
	11/4	12-1965
	11/2	12-1966
	2	12-1968
	21/2	12-1969
10	1/2	12-1971
	34	12-1973
	1	12-1974
	11/4	12-1975
	11/2	12-1976
	134	12-1977
Continued On Next Column		

Size	Length	Qty/Box Part No.
		0
Stainless Pan He	ad Type A Tap	ping Screws Continued
12	1/2	12-1981
	34	12-1983
	1	12-1984
	114	12-1985
	11/2	12-1986
	2	12-1988
14	1	12-1994
	114	12-1995
	11/2	12-1996

	9	
Stainless Set	Screws	
10-24	34	12-2940
	3/8	12-2942
14-20	34	12-2901
14-20	3/8	12-2903
14-28	34	12-2902
(Phillips) 100	per box.	

Stainless Thr	eaded Rod	10
14-20	3'	12-29
%6-18	3'	12-29

 ¼-20
 3'
 12-2956

 ¾6-18
 3'
 12-2959

 ¾6-16
 3'
 12-2962

 Three foot length only.



Flat Head W	ood Screws	100
6	11/4	12-3209
8	11/2	12-3215
10	11/4	12-3220
	11/2	12-3221
(Frearson) sil Use R & P dr	icon bronze. 100 iver.	per box.

(		
Flat Head W	ood Screws	
12	11/2	12-415

Flat Head Wo	ood Screws		
12	11/2		12-4154
	21/2		12-4157
(Phillips) stai	nless steel.	100 per box.	

Metric Flat Stainless Washer

12-3714

10mm

Size	Length	Qty/Box	Part No.
	•		
Fender Stai	nless Washe		
#10		100	12-2832
1/4		100	12-2828
5/16		100	12-2829
3/6		100	12-2830
100 per box.			

Flat Stainless Washer		
8	100	12-2825
10	100	12-2826
12	100	12-2827
1/4	100	12-2815
546	100	12-2816
36	100	12-2817
7/16	50	12-2818
1/2	50	12-2819

Lock Stainless Washer		
10	100	12-2844
1/4	100	12-2833
5/16	100	12-2834
<del>3</del> /a	100	12-2835
1/2	50	12-2837

Finishing Stainless Washer		
#8	100	12-2849
#10	100	12-2850
#12	100	12-2851
34	100	12-2846
546	100	12-2847
100 per box.		

*	t to	
Star Stainless Wa	sher	
5/16	100	12-2324
34	100	12-2831
100 per box.		